

Information:

Drawer: Accounts Payable - Invoices
Vendor Number: 1313674
Vendor Name: Advanced Parts & Services
Invoice Number: 210826
Invoice Date: 11/30/20
PO Number: PO371862
Check Number: E0082770
Check Amount: \$ 3,417.00
Check Date: 01/06/2021
Department ID: 13160
Reviewer Name: None
Voucher Number: V0656257
Redaction Type: None
Document Type: AP Invoice

Document Below

From: karla@apands.com
Sent: Fri Dec 04 10:34:59 CST 2020
To: erll630@cod.edu,invoicing@cod.edu
CC:
Subject: Invoice[210826]: Work Order 2008452 Service

Hello,

Attached is your Invoice for walk in freezer service not temping.

Thank you,
Karla I
12/4/2020
Advanced Parts Service
1800 Parkes Drive
Broadview, IL 60155
708-354-7400
www.APandS.com



Parts, Service
& Installation
of Food Service
Cooking and
Refrigeration Equipment:
www.APANDS.com

1800 Parkes Drive, Broadview, IL 60155
Phone: 800-339-7402 Fax: 708-354-7424

Invoice # : 210826

Invoice Date : 11/30/2020

Customer PO :

Work Order # : 2008452

Bill To : 2908

Location : 2908

College of DuPage
425 Fawell Blvd
Glen Ellyn, IL 60137

College of DuPage
425 Fawell Blvd
Glen Ellyn, IL 60137

Request By

Call Type

Terms

Technician

*T&M w/ Travel

NET 60

AL J

Service Performed :

Invoice for walk in freezer service not temping. Arrived and checked in with David and went thru screening process. Found walk in freezer box at 35 degrees. Fans were off when I arrived and was in a defrost. Checked evaporator for ice up but was clear of ice. Some ice build up at bottom of coil like it was ice up. Replaced Fan and service gauges in system and found unit low on refrigerant. Low pressure switch was open. Added charge to system to get unit going. Unit is at 10 degrees and dropping down in temperature. Will have to return and follow up to leak check system and replace filter drier. Arrived and checked in with screeners at entry and Dave from engineering. Checked freezer and found breaker had tripped due to bad contactor. Pumped system down and replaced leaking accumulator and filter drier. Also replaced bad three pole contactor. Nitrogen leak tested and vacuumed system. Added charge to system and watch unit operation. waited for unit to drop down to temperature and cycle compressor on and off. Cleared sight glass and added winter charge to system. Unit is operating correctly and box is down to temperature.

Item	Description	Quantity	Price	Extended
Labor	Labor		96.00	\$960.00
	Labor, Travel		96.00	\$192.00
	Labor		96.00	\$216.00
	Labor		96.00	\$312.00
	Labor, Travel		96.00	\$96.00
Parts	ADV 042 404A Refrigerant, HP62, LB	4.00	36.05	\$144.20
	ADV 042 404A Refrigerant, HP62, LB	6.00	36.05	\$216.30
	ADV 198 Torch, Nitrogen, Vacuum, Solder, Recover	1.00	156.00	\$156.00
	ADV 042 404A Refrigerant, HP62, LB	8.00	36.05	\$288.40
	ADV 221 - Filter Drier, C-163S	1.00	52.00	\$52.00
	COP 577-0421-01 - Suction Line Accumulator	1.00	428.30	\$428.30
	ADV 1000 - Plumbing Material	1.00	44.85	\$44.85
	ADV C340C - 3-Pole Contactor, 40Amp, 208/240V	1.00	46.00	\$46.00
	ADV 507 - Service Ladder Charge	2.00	75.00	\$150.00
Miscellaneous	Travel	1.00	96.00	\$96.00
Freight	Freight	1.00	18.95	\$18.95



Invoice # : 210826

Invoice Date : 11/30/2020

Customer PO :

Work Order # : 2008452

Bill To : 2908

College of DuPage
425 Fawell Blvd
Glen Ellyn, IL 60137

Location : 2908

College of DuPage
425 Fawell Blvd
Glen Ellyn, IL 60137

Item	Description	Quantity	Price	Extended
------	-------------	----------	-------	----------

Commercial Foodservice Equipment

Service - Replacement Parts - Contracts - Repair
Warranty Service - New Installation - Warehousing
Remodeling - Consolidation - Delivery
Preventative Maintenance
Gas - Steam - Electric - Refrigeration

www.APandS.com

Item :	\$1,526.05
Freight :	\$18.95
Labor :	\$1,776.00
Miscellaneous :	\$96.00
Sales Tax :	\$0.00
Total :	\$3,417.00
Paid :	\$0.00
Balance Due :	\$3,417.00