

Information:

Drawer: Accounts Payable - Invoices  
Vendor Number: 1255711  
Vendor Name: Windy City Truck Repair, Inc  
Invoice Number: IN00129791  
Invoice Date: 10/27/2022  
PO Number: B0000954  
Check Number: 0307309  
Check Amount: \$ 768.35  
Check Date: 01/18/2023  
Voucher Number: V0767215  
Document Type: AP Invoice

Document Below

WINDY CITY TRUCK REPAIR  
61 S. MITCHELL CT.

ADDISON, IL 60101  
(630) 629-9009

\*\*Original\*\* - Copy2

TYPE  
IN

Invoice #  
IN00129791

Date  
10/27/2022 15:12

By  
SB

Account  
COL001

Name - Address  
COLLEGE OF DUPAGE  
301 SWIFT  
DOOR #6  
ADDISON, IL 60101

Contact  
JIM V

H. (630)942-2275  
W. (630)942-2275  
M. (847)840-3789

License #  
BF7968

Year - Model  
12 FREIGHTLINER #1012

Color

Mileage  
636376

Engine Inspection Date

PO Number : B0000945

Tag Number :

VIN # : BF7968

Item	Description	Qty	Parts	Labor FET / Core	TC	Extension
7909	OIL FILTER,MERCEDES CARTR	1.00	44.50		JS	44.50
600103	FUEL FILTER KIT,DD15	1.00	120.30		JS	120.30
FFF	FUEL FILTER FUEL	1.00	0.50		JS	0.50
15W40	15W40 OIL QUART,PHILLIPS	44.00	4.89		JS	215.16
GREASE	GREASE,RED HI-TEMP	1.00	5.95		JS	5.95
ATF	FLUID,TRANSMISSION & P/S	1.00	5.72		JS	5.72
75W90S	SYNTHETIC GEAR LUBE,ESI	4.00	5.95		JS	23.80
HD1P	ANTIFREEZE,E.S 1/2 GALLON	1.00	8.18		JS	8.18
WW	WASHER FLUID	2.00	4.36		JS	8.72
8017830	DIAPHRAM #30 LONG STROKE	1.00	9.51		JS	9.51
8216045P	CHAMBER CLAMP,TYPE 30	1.00	13.71		JS	13.71
58N	NUT	2.00	0.90		JS	1.80
58W	WASHER	2.00	0.50		JS	1.00
MIS2	SHOP SUPPLIES	1.00	2.00		JS	2.00
1.0	LABOR HOUR	1.50		120.00	JS	180.00
1.0PM	P.M. LABOR HOUR	1.50		85.00	JS	127.50
	R.O.#93603					
	PO# B0000945					

Estimate :

Revised :

2nd Rev :

Promised :

Auth by :

Telephone :

Auth by :

Telephone :

Totals

Parts	460.85
Labor	307.50
Other	
FET/Core	
Subtotal	768.35
Tax	0.00
Total	768.35

Cash :

Check :

Cr Cd :

Chrg : 768.35

# WINDY CITY TRUCK REPAIR, Inc.

61 S. Mitchell Court

ADDISON, ILLINOIS 60101

Phone: 629-9009

No 93603

DATE

10/22/22

WRITTEN BY

Alond

C.O.D.

B  
I  
L  
T  
O

6/11  
MONTANA

SERIAL NUMBER

R5C\$BF7968

☐ WARRANTY ☐ INTERNAL  
☐ CASH ☐ CHARGE

MILEAGE

636376 1012

UNIT NO.

CUSTOMER PO. NO.

PHONE

TIME PROMISED

A.M.  
P.M.

DESCRIPTION OF WORK

① Repair Air Leak - Possible Steel Cracks

185 -

LABOR

② P.M. Service

127.50

TERMS: STRICTLY CASH UNLESS OTHER ARRANGEMENTS HAVE BEEN MADE PRIOR TO BEGINNING OF REPAIRS TO BE PERFORMED. YOU ARE HEREBY INSTRUCTED TO MAKE ABOVE REPAIRS AND ANY ADDITIONAL REPAIRS, IF NECESSARY, FOR WHICH THE UNDERSIGNED PROMISES TO PAY IN FULL UPON DELIVERY, I UNDERSTAND AN EXPRESS MECHANIC'S LIEN IS ACKNOWLEDGED ON VEHICLE TO SECURE THE AMOUNT OF REPAIRS THERETO. YOU AND YOUR EMPLOYEES MAY OPERATE VEHICLE FOR PURPOSES OF TESTING, INSPECTION, OR DELIVERY AT MY RISK.

YOU WILL NOT BE HELD RESPONSIBLE FOR LOSS OR DAMAGE TO VEHICLE OR ARTICLES LEFT IN VEHICLE IN CASE OF FIRE, THEFT, ACCIDENT OR ANY OTHER CAUSE BEYOND YOUR CONTROL.

ANY CUSTOMER PARTS NOT PICKED UP BY CUSTOMER WITHIN 30 DAYS AFTER DELIVERY OF VEHICLE TO CUSTOMER SHALL BE DEEMED OF NO VALUE AND SHALL BE DISPOSED OF AS WINDY CITY TRUCK REPAIR, INC. SEES FIT WITHOUT ANY OBLIGATION TO THE CUSTOMER.

PLEASE REMIT TO:

WINDY CITY TRUCK REPAIR, Inc.

61 S. Mitchell Court

ADDISON, ILLINOIS 60101

SUMMARY

LABOR

HRS. @ \$

/HR.

\$

PARTS

\$

SUBLET

\$

MISC. PARTS SUPPLIES

\$

LUBE OIL

\$

GEAR LUBE

\$

Please See

Attached

Invoice

SALES TAX/STATE

TOTAL

187.50


\$

768.35

X

AUTHORIZED BY

I.C.C. #



## PM SERVICE SHEET

COMPANY NAME WCD DATE 10-24-22 RO# 43603  
 UNIT# 1012 MILEAGE 63,000 MAKE Freight MODEL  YEAR 6/11  
 VIN R5CJBF2968

	OK	NEEDS REPAIR
1. CHANGE OIL AND FILTERS	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. CHANGE ALL FUEL FILTERS	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. LUBE CHASSIS AND CHECK FOR BAD FITTINGS	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. CHECK FRONT END WEAR-JACK UP AND CHECK KING PINS	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. CHECK STEER AXLE HUB LEVELS	<input checked="" type="checkbox"/>	<input type="checkbox"/>
6. CHECK COOLANT LEVEL	<input checked="" type="checkbox"/>	<input type="checkbox"/>
7. CHECK FOR COOLING SYSTEM LEAKS	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. CHECK ALL BELTS AND HOSES	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. CHECK POWER STEERING FLUID LEVEL--CHECK FOR LEAKS	<input checked="" type="checkbox"/>	<input type="checkbox"/>
10. CHECK FOR ENGINE OIL LEAKS	<input checked="" type="checkbox"/>	<input type="checkbox"/>
11. CHECK TRANSMISSION LEVEL -- CHECK FOR LEAKS	<input checked="" type="checkbox"/>	<input type="checkbox"/>
12. CHECK CLUTCH ADJUSTMENT	<input checked="" type="checkbox"/>	<input type="checkbox"/>
13. CHECK DIFFERENTIAL LEVELS <input checked="" type="checkbox"/> CHECKS FOR LEAKS	<input checked="" type="checkbox"/>	<input type="checkbox"/>
14. CHECK BRAKE ADJUSTMENT AND SHOE THICKNESS	<input checked="" type="checkbox"/>	<input type="checkbox"/>
15. CHECK ALL SPRINGS FOR CRACKS OR WEAR	<input checked="" type="checkbox"/>	<input type="checkbox"/>
16. CHECK TIRE CONDITION	<input checked="" type="checkbox"/>	<input type="checkbox"/>
17. CHECK FIFTH WHEEL CONDITIONS AND CHECK FOR CRACKS	<input checked="" type="checkbox"/>	<input type="checkbox"/>
18. CHECK TRAILER AIR HOSES AND LIGHT CORD CONDITIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>
19. DRAIN WATER FROM AIR TANKS	<input checked="" type="checkbox"/>	<input type="checkbox"/>
20. INSPECT FOR BODY DAMAGE	<input checked="" type="checkbox"/>	<input type="checkbox"/>
21. CHECK ALL GLASS FOR CRACKS OR DAMAGE	<input checked="" type="checkbox"/>	<input type="checkbox"/>
22. CHECK ALL LIGHTS FOR OPERATION	<input checked="" type="checkbox"/>	<input type="checkbox"/>
23. CHECK BATTERIES AND CABLES FOR CLEANLINESS---LEVEL	<input checked="" type="checkbox"/>	<input type="checkbox"/>
24. CHECK AIR CLEANER ELEMENT	<input checked="" type="checkbox"/>	<input type="checkbox"/>
25. CHECK PARKING BRAKE OPERATION	<input checked="" type="checkbox"/>	<input type="checkbox"/>
26. CHECK AIR SYSTEM WARNING DEVICES	<input checked="" type="checkbox"/>	<input type="checkbox"/>
27. CHECK FOR SAFETY EQUIPMENT/ WARNING DEVICES/ FLARES	<input checked="" type="checkbox"/>	<input type="checkbox"/>
28. CHECK FOR PROPER SEAT BELT OPERATION	<input checked="" type="checkbox"/>	<input type="checkbox"/>
29. CHECK FOR AIR LEAKS WITH BRAKES APPLIED	<input checked="" type="checkbox"/>	<input type="checkbox"/>
30. CHECK AIR AND CITY HORN OPERATION	<input checked="" type="checkbox"/>	<input type="checkbox"/>

P 20 0/0  
 %  
 PD 20 0/0  
 D 20 0/0

washer tank broken.  
 front line engine wet from head down  
 trans wet at back of motor  
 PD 20 low leaking from input seal

Jen Anzelmo <JenWindyCityTruck@hotmail.com>

---

[External] 129791

---

Jen Anzelmo <JenWindyCityTruck@hotmail.com>

Mon, Oct 31, 2022 at 08:02 PM GMT

CC: Vegetabile, Jim <vegetabilej@cod.edu>

BCC:

CAUTION: This email originated from outside of COD's system. Do not click links, open attachments, or respond with sensitive information unless you recognize the sender and know the content is safe.

Hello  
invoice copy attached  
Thank you!

Jennifer Anzelmo  
Windy City Truck Repair  
61 South Mitchell Court  
Addison, IL 60101  
Ph:630-629-9009  
Fx:630-932-7560

---

**1 attachment**

129791.pdf