

Information:

Drawer: Accounts Payable - Invoices
Vendor Number: 1255711
Vendor Name: Windy City Truck Repair, Inc
Invoice Number: IN00130841
Invoice Date: 2/24/2023
PO Number: B0001280
Check Number: 0311914
Check Amount: \$ 2,044.14
Check Date: 05/09/2023
Voucher Number: V0783091
Document Type: AP Invoice

Document Below

WINDY CITY TRUCK REPAIR
61 S. MITCHELL CT.

ADDISON, IL 60101
(630) 629-9009

****Original** - Copy2**

TYPE	Invoice #	Date	By
IN	IN00130841	02/24/2023 9:54	SB

Account	Name - Address	Contact
COL001	COLLEGE OF DUPAGE 301 SWIFT DOOR #6 ADDISON, IL 60101	JIM V H. (630)942-2275 W. (630)942-2275 M. (630)942-2275

License #	Year - Model	Color	Mileage	Engine	Inspection Date
GL0315	15 FREIGHTLINER #1017	07/14	603821		

PO Number :	B0000954	Tag Number :	VIN # : GL0315
-------------	----------	--------------	----------------

Item	Description	Qty	Parts	Labor FET / Core	TC	Extension
8017830	DIAPHRAM #30 LONG STROKE	1.00	9.57		JS	9.57
8216045P	CHAMBER CLAMP,TYPE 30	1.00	16.58		JS	16.58
1.0	LABOR HOUR	1.00		120.00	JS	120.00
	RO#94379					

PO# B0000954

Estimate :		Promised :
Revised :	Auth by :	Telephone :
2nd Rev :	Auth by :	Telephone :

Totals

Parts	26.15
Labor	120.00
Other	
FET/Core	
Subtotal	146.15
Tax	0.00
Total	146.15

Cash :	Check :	Cr Cd :	Chrg :	146.15
--------	---------	---------	--------	--------

Shawna Dye <shawnawindycitytruck@hotmail.com>

[External] 2015 Freightliner #1017 PO# B0000954

Shawna Dye <shawnawindycitytruck@hotmail.com>

Fri, Feb 24, 2023 at 06:50 PM UTC

CC:

BCC:

CAUTION: This email originated from outside of COD's system. Do not click links, open attachments, or respond with sensitive information unless you recognize the sender and know the content is safe.

Hello,

Please see the attached for your most recent invoice.

Thanks,

Shawna Dye
Windy City Truck Repair
61 S. Mitchell Ct
Addison, IL 60101
ph:630-629-9009
fax:630-932-7560

2 attachments

C.O.D. 130841 (1).pdf

C.O.D. 130841 (2).pdf

Information:

Drawer: Accounts Payable - Invoices
Vendor Number: 1255711
Vendor Name: Windy City Truck Repair, Inc
Invoice Number: IN00130318
Invoice Date: 1/17/2023
PO Number: B0001280
Check Number: 0311914
Check Amount: \$ 2,044.14
Check Date: 05/09/2023
Voucher Number: V0783978
Document Type: AP Invoice

Document Below

WINDY CITY TRUCK REPAIR
61 S. MITCHELL CT.

ADDISON, IL 60101
(630) 629-9009

****Original** - Copy1**

TYPE	Invoice #	Date	By
IN	IN00130318	01/17/2023 11:27	SB

Account	Name - Address	Contact	
COL001	COLLEGE OF DUPAGE	JIM V	
	301 SWIFT		H. (630)942-2275
	DOOR #6		W. (630)942-2275
	ADDISON, IL 60101		M. -

License #	Year - Model	Color	Mileage	Engine	Inspection Date
HN4502	16 FREIGHTLINER #1013		415016		

PO Number :	B0000954	Tag Number :	VIN # :	HN4502
-------------	----------	--------------	---------	--------

Item	Description	Qty	Parts	Labor FET / Core	TC	Extension
H11	BULB,HEADLIGHT	1.00	21.81		JS	21.81
787143	HEADLIGHT HARNESS,2-TERMINAL	1.00	16.60		JS	16.60
40700	GROMMET,ROUND LIGHT	1.00	3.51		JS	3.51
4058	TAIL LIGHT,4" RED L.E.D.	1.00	26.06		JS	26.06
94993	PIGTAIL	1.00	3.47		JS	3.47
9935	ELE. CONNECTOR W/HEAT SHR	5.00	0.96		JS	4.80
XK2124711QP	BRAKE SHOE KIT,REAR AXLE	2.00	117.02		JS	234.04
N42A1658625B	BRAKE DRUM,REAR AXLE 8.58	2.00	338.97		JS	677.94
94	PARTS CLEANER	1.00	6.20		JS	6.20
765-1351P	SYLGLIDE LUBE	1.00	3.56		JS	3.56
1.0	LABOR HOUR	7.50		120.00	JS	900.00
	RO#93977					

PO# B0000954

Estimate :	Promised :
------------	------------

Revised :	Auth by :	Telephone :
-----------	-----------	-------------

2nd Rev :	Auth by :	Telephone :
-----------	-----------	-------------

Totals


Parts	997.99
Labor	900.00
Other	
FET/Core	
Subtotal	1,897.99
Tax	0.00
Total	1,897.99

Cash :	Check :	Cr Cd :	Chrg :	1,897.99
--------	---------	---------	--------	----------



This report remains the property of the Illinois Department of Transportation. A copy must be filed numerically and chronologically at the Official Testing Station for a period of (18) eighteen months and must be available for inspection by employees of Illinois Department of Transportation. Mark each field below Pass or Fail with an "X". If an item on this form does not apply, leave it blank. The Submission of this form certifies the accuracy and completeness of the inspection in accordance with 49 CFR 396.21. This inspection does not meet USDOT motorcoach inspection.

Vehicle Inspection Report

 accordance with 49 CFR 396.21 This inspection does not meet USDOT motor carrier inspection.											
1. <input checked="" type="checkbox"/> 6 Month	3. US DOT Number	4. <input type="checkbox"/> Reject over 30	6. Station	7. License Plate	8. Vehicle Identification Number	9. Certificate of Safety Number					
2. <input type="checkbox"/> 12 Month		5. <input type="checkbox"/> Replacement CS	0156	M221878	3AKJGLBG5GSHN4502						
10. Company Name		11. Company City		12. Odometer Reading		13. Date of Test		14. Time Started		15. Time Ended	
COLLEGE OF DUPAGE		GLEN ELLYN		414,997		12/09/22		1:11 <input type="checkbox"/> AM <input checked="" type="checkbox"/> PM		1:21 <input type="checkbox"/> AM <input checked="" type="checkbox"/> PM	
16. Model Year	17. Vehicle Type	18. Trailer Make		19. Vehicle Make	20. Single Wheel Axle	1	4. Test Fee	23. Date C/S Applied		24. Time C/S Applied	
2016	CDL Training			FREIGHTLINER	21. Double Wheel Axle	2	\$59.50			<input type="checkbox"/> AM <input type="checkbox"/> PM	
25. CST Name		26. CST Signature			27. CST ID#		28. Retest CST Name		29. Retest Signature		
Robert Morales					30				30. Retest CST ID#		

Brakes

Pass	Fail :
X	
X	
X	
X	
X	
X	X
X	
X	
X	
X	

Exterior	
Pass	Fail

Back up Alarm (Refuse Hauler Only)

Pass	Fail
X	
X	
X	

**Adjustable Axle Assemblies
Cracked or Broken Members
Loose or Missing Fasteners
Tire Wheel Clearance**

Pass	Fail
X	
X	
X	

Missing or Loose Components

Pass	Fail
X	

Brake Failure Indicator Light	
Low pres./Vacuum Warning Device	
Ind Light	

Pass	Fail
X	

Engine and Underbody Components	
Pass	Fail
X	

Air Compressor

Exhaust System	
Pass	Fail
X	
X	

Leaks
Located as not to cause damages

Discharge Excess 6" Forward from Rear

Bus - Other than Gas Powered		
Discharge Excess 15" Forward from Rear		
Discharge Forward of Door or Opening Window		

Pass	Fail
X	

	Cargo Secure
	Front End Structure

X	X	X	X	X

Improper Load, Size, or Use
Mismatch Radial or Bias
Regrooved (Unless Urban or Suburban)
Tire Condition
Tread Depth

[illegible]

- Ball and Socket Joint
- Binding, Jamming or Loose Parts
- Drag Links
- Free Play
- Pitman Arm
- Power Assist Unit
- Steering Column
- Steering Gear Box
- Steering System Modification
- Steering Wheel
- Tie Rod

Suspension	
Pass	Fail
X	
X	
X	

- Air Suspension
- Axle Positioning Parts
- Coil Spring
- Rubber Springs
- Springs or Shackles
- TorqueRadius/Tracing Components

Pass	Fail
X	
X	
X	
X	
X	

Contact with Vehicle
 Flat or Leak
 Tire Condition
 Tread Depth
 Improper Load, Size, or Use

Tires-Steering Axle	
Pass	Fail

1000

[illegible]

Special Vehicles Only

Windshield Wipers	
Pass	Fail
X	

Windshield Wipers

Pass	Fail
X	
X	
X	

Windshield

Pass	Fail
X	

Windshield

Battery
Body
Bumper
Color
Door or Latches
Dual Brake
Emergency Exits
Fire Extinguisher
Heater or Defroster
Horn
Hoses or Cables
King Pins
Lettering
Mirrors
Muffler
Seal Anchoring
Seal Belt
Shocks and Struts
Splash Guards
Steps or Floor Covering
Warning Devices
Wheel Alignment
Wheel Bearing
Window other than Windshield
Windshield Washer

Remarks

HEADLIGHT OUT PASSENGER SIDE RIGHT REAR TURN SIGNAL IS ON DRIVER SIDE REAR TURN SIGNAL IS ON

BIC 3000 (Rev 12/08/17)

Shawna Dye <shawnawindycitytruck@hotmail.com>

[External] PO# B0000954 IN# 130318

Shawna Dye <shawnawindycitytruck@hotmail.com>

Tue, Jan 17, 2023 at 05:33 PM UTC

CC:

BCC:

CAUTION: This email originated from outside of COD's system. Do not click links, open attachments, or respond with sensitive information unless you recognize the sender and know the content is safe.

Hello,

Please see the attached document for the invoice and inspection report on unit # 1013.

Thanks,

Shawna Dye
Windy City Truck Repair
61 S. Mitchell Ct
Addison, IL 60101
ph:630-629-9009
fax:630-932-7560

1 attachment

COD 130318.pdf