

Information:

Drawer: Accounts Payable - Invoices
Vendor Number: 1087084
Vendor Name: Northern Illinois Backflow
Invoice Number: 32563
Invoice Date: 1/4/2023
PO Number: B0001207
Check Number: E0094324
Check Amount: \$ 5,303.70
Check Date: 03/22/2023
Voucher Number: V0779565
Document Type: AP Invoice

Document Below



Northern Illinois Backflow

1601 Atlantic Drive Ste. 101
West Chicago, IL 60185

Invoice

Date	Invoice #
1/4/2023	32563

Bill To
College of DuPage Accounts Payable, SRC2049 425 Fawell Blvd Glen Ellyn, IL 60137

Ship To
College of DuPage VARIOUS LOCATIONS

	Purchase Order	Rep	Tech	Terms	Due Date
	B0001207	LS	KJ&BD	Net 30	2/3/2023
Item	Description	Invoiced	Rate	Amount	
Annual Backflow - ...	Glen Ellyn Campus- 425 Farwell Blvd Glen Elly, IL 60137 Tested 122 backflow devices, 119 passed 3 failed. Results have been forwarded to Aqua Backflow. Estimate for repair to follow.	122	28.50	3,477.00	
Aqua- Glen Ellyn	Aqua Backflow Filing Fee- Glen Ellyn NOTE: Add \$10 late fee per device if tested late	122	9.95	1,213.90	
Annual Backflow - ...	Westmont Campus- 650 Pasquinelli Dr. Westmont, IL 60559 Tested 5 backflow devices, and they all passed tests. Results have been forwarded to BSI.	5	28.50	142.50	
BSI- Westmont	BSI Online filing fee- Westmont	5	16.95	84.75	
Annual Backflow - ...	Naperville Campus- 1223 Rickert Drive Naperville, IL 60540 Tested 5 backflow devices, 4 passed one failed. Results have been forwarded to Aqua Backflow. Estimate for repair to follow.	5	28.50	142.50	
Aqua- Naperville	Aqua Backflow Filing Fee- Naperville	5	9.85	49.25	
Annual Backflow - ...	Carol Stream Campus- 500 N. Kuhn Road Carol Stream, IL 60188 Tested 4 backflow devices, and they all passed tests. Results have been forwarded to BSI.	4	28.50	114.00	
BSI- Carol Stream	BSI Online filing fee- Carol Stream	4	14.95	59.80	
Fuel Surcharge	Fuel Surcharge Administrative Fee Will be Added to All Payments Made by Credit Card	1	20.00	20.00	

Total \$5,303.70

Payments/Credits \$0.00

Balance Due \$5,303.70

Phone #	Fax #	E-mail	Web Site
630-231-1595	630-231-0550	service@nibackflow.com	www.nibackflow.com



1601 Atlantic Drive

Suite 101

West Chicago, IL 60185

(630) 231-1595

fax: (630) 231 - 0550

www.nibackflow.com

Service Address

Address: 500 N. Kuhn Road
Company: College of DuPage (Carol Stream)
City: Carol Stream
Hazard: BOILER
Location: Mechanical Room

Serial #: W127197
Manufacturer: WILKINS
Model: 975XL
Type: RP
Size: 0.750
Hazard #: 1 of 4

	Reduced Pressure Principle Assembly			RP <input checked="" type="checkbox"/> DCDA <input type="checkbox"/> DC <input type="checkbox"/> RPDA <input type="checkbox"/> PVB <input type="checkbox"/> Air Gap <input type="checkbox"/> SVB <input type="checkbox"/> AVB <input type="checkbox"/>
	Double Check Valve Assembly			
	Check Valve #1	Check Valve #2	Relief Valve	PVB/SVB
Initial Test	Leaked <input type="checkbox"/> Closed Tight <input checked="" type="checkbox"/> Held at <u>8.8</u> PSID	Leaked <input type="checkbox"/> Closed Tight <input checked="" type="checkbox"/> Held at <u>8.6</u> PSID	Did not Open <input type="checkbox"/> Opened at <u>2.4</u> PSID	AIR INLET Did not Open <input type="checkbox"/> Opened at _____ PSID
			Buffer <u>6.4</u> PSID	CHECK VALVE Leaked <input type="checkbox"/> Held at _____ PSID
Repairs	Repaired <input type="checkbox"/>			Repaired <input type="checkbox"/>
Final Test	Closed Tight <input type="checkbox"/> Held at _____ PSID	Closed Tight <input type="checkbox"/> Held at _____ PSID	Opened at _____ PSID	AIR INLET Opened at _____ PSID CHECK VALVE Held at _____ PSID
			Buffer _____ PSID	Held at _____ PSID

Comments

The above report is certified to be true.

Line Pressure _____
 Held Backpressure ☒
 #2 Shutoff ☒
 Relief Valve Exercised ☒

	Date/Time	Tester	Signature	Tester #	Test Kit	Passed	Failed
Initial Test	01/04/23	Jason Nyberg		XC5236	01180720	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Repairs							
Final Test						<input type="checkbox"/>	<input type="checkbox"/>



1601 Atlantic Drive Suite 101 West Chicago, IL 60185 (630) 231-1595 fax: (630) 231 - 0550 www.nibackflow.com

Service Address

Address: 500 N. Kuhn Road
Company: College of DuPage (Carol Stream)
City: Carol Stream
Hazard: FIRE SERVICE
Location: Sprinkler Room

Serial #: DL-0496
Manufacturer: AMES
Model: MAXIM 300
Type: DC
Size: 4.000
Hazard #: 2 of 4

Reduced Pressure Principle Assembly				RP <input type="checkbox"/> DCDA <input type="checkbox"/> DC <input checked="" type="checkbox"/> RPDA <input type="checkbox"/> PVB <input type="checkbox"/> Air Gap <input type="checkbox"/> SVB <input type="checkbox"/> AVB <input type="checkbox"/>
Double Check Valve Assembly				
	Check Valve #1	Check Valve #2	Relief Valve	PVB/SVB
Initial Test	Leaked <input type="checkbox"/> Closed Tight <input checked="" type="checkbox"/> Held at 3.2 PSID	Leaked <input type="checkbox"/> Closed Tight <input checked="" type="checkbox"/> Held at 3.0 PSID	Did not Open <input type="checkbox"/> Opened at _____ PSID	AIR INLET Did not Open <input type="checkbox"/> Opened at _____ PSID
			Buffer _____ PSID	CHECK VALVE Leaked <input type="checkbox"/> Held at _____ PSID
Repairs	Repaired <input type="checkbox"/>			Repaired <input type="checkbox"/>
Final Test	Closed Tight <input type="checkbox"/> Held at _____ PSID	Closed Tight <input type="checkbox"/> Held at _____ PSID	Opened at _____ PSID Buffer _____ PSID	AIR INLET Opened at _____ PSID CHECK VALVE Held at _____ PSID

Comments

The above report is certified to be true.	Line Pressure _____
	Held Backpressure <input checked="" type="checkbox"/>
	#2 Shutoff <input checked="" type="checkbox"/>
	Relief Valve Exercised <input type="checkbox"/>

	Date/Time	Tester	Signature	Tester #	Test Kit	Passed	Failed
Initial Test	01/04/23	Jason Nyberg		XC5236	01180720	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Repairs							
Final Test						<input type="checkbox"/>	<input type="checkbox"/>



1601 Atlantic Drive Suite 101 West Chicago, IL 60185 (630) 231-1595 fax: (630) 231 - 0550 www.nibackflow.com

Service Address

Address: 500 N. Kuhn Road
 Company: College of DuPage (Carol Stream)
 City: Carol Stream
 Hazard: FIRE SRV BYPASS
 Location: Sprinkler Room

Serial #: 34870
 Manufacturer: AMES
 Model: 2000B
 Type: DC
 Size: 0.750
 Hazard #: 3 of 4

Reduced Pressure Principle Assembly				RP <input type="checkbox"/> DCDA <input type="checkbox"/> DC <input checked="" type="checkbox"/> RPDA <input type="checkbox"/> PVB <input type="checkbox"/> Air Gap <input type="checkbox"/> SVB <input type="checkbox"/> AVB <input type="checkbox"/>
Double Check Valve Assembly				
	Check Valve #1	Check Valve #2	Relief Valve	PVB/SVB
Initial Test	Leaked <input type="checkbox"/> Closed Tight <input checked="" type="checkbox"/> Held at 2.4 PSID	Leaked <input type="checkbox"/> Closed Tight <input checked="" type="checkbox"/> Held at 2.2 PSID	Did not Open <input type="checkbox"/> Opened at _____ PSID	AIR INLET Did not Open <input type="checkbox"/> Opened at _____ PSID
			Buffer _____ PSID	CHECK VALVE Leaked <input type="checkbox"/> Held at _____ PSID
Repairs	Repaired <input type="checkbox"/>			Repaired <input type="checkbox"/>
Final Test	Closed Tight <input type="checkbox"/> Held at _____ PSID	Closed Tight <input type="checkbox"/> Held at _____ PSID	Opened at _____ PSID Buffer _____ PSID	AIR INLET Opened at _____ PSID CHECK VALVE Held at _____ PSID

Comments	Line Pressure _____
	Held Backpressure <input checked="" type="checkbox"/>
	#2 Shutoff <input checked="" type="checkbox"/>
	Relief Valve Exercised <input type="checkbox"/>

The above report is certified to be true.

	Date/Time	Tester	Signature	Tester #	Test Kit	Passed	Failed
Initial Test	01/04/23	Jason Nyberg		XC5236	01180720	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Repairs							
Final Test						<input type="checkbox"/>	<input type="checkbox"/>



1601 Atlantic Drive Suite 101 West Chicago, IL 60185 (630) 231-1595 fax: (630) 231 - 0550 www.nibackflow.com

Service Address

Address: 500 N. Kuhn Road
 Company: College of DuPage (Carol Stream)
 City: Carol Stream
 Hazard: DOM WATER
 Location: Sprinkler Room

Serial #: 0125141
 Manufacturer: WILKINS
 Model: 975XL
 Type: RP
 Size: 2.000
 Hazard #: 4 of 4

Reduced Pressure Principle Assembly				RP <input checked="" type="checkbox"/> DCDA <input type="checkbox"/> DC <input type="checkbox"/> RPDA <input type="checkbox"/> PVB <input type="checkbox"/> Air Gap <input type="checkbox"/> SVB <input type="checkbox"/> AVB <input type="checkbox"/>
Double Check Valve Assembly				
	Check Valve #1	Check Valve #2	Relief Valve	PVB/SVB
Initial Test	Leaked <input type="checkbox"/> Closed Tight <input checked="" type="checkbox"/> Held at <u>8.6</u> PSID	Leaked <input type="checkbox"/> Closed Tight <input checked="" type="checkbox"/> Held at <u>8.4</u> PSID	Did not Open <input type="checkbox"/> Opened at <u>2.0</u> PSID	AIR INLET Did not Open <input type="checkbox"/> Opened at _____ PSID
			Buffer <u>6.6</u> PSID	CHECK VALVE Leaked <input type="checkbox"/> Held at _____ PSID
Repairs	Repaired <input type="checkbox"/>			Repaired <input type="checkbox"/>
Final Test	Closed Tight <input type="checkbox"/> Held at _____ PSID	Closed Tight <input type="checkbox"/> Held at _____ PSID	Opened at _____ PSID	AIR INLET Opened at _____ PSID CHECK VALVE Held at _____ PSID
			Buffer _____ PSID	

Comments

The above report is certified to be true.

Line Pressure _____
 Held Backpressure ☒
 #2 Shutoff ☒
 Relief Valve Exercised ☒

	Date/Time	Tester	Signature	Tester #	Test Kit	Passed	Failed
Initial Test	01/04/23	Jason Nyberg		XC5236	01180720	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Repairs							
Final Test						<input type="checkbox"/>	<input type="checkbox"/>



1601 Atlantic Drive Suite 101 West Chicago, IL 60185 (630) 231-1595 fax: (630) 231 - 0550 www.nibackflow.com

Service Address

Address: 1223 Rickert Drive
 Company: College of DuPage (Naperville)
 City: Naperville
 Hazard: BOILER
 Location: Basement Mechanical Room

Serial #: 018831
 Manufacturer: WILKINS
 Model: 975
 Type: RP
 Size: 0.750
 Hazard #: 1 of 7

	Reduced Pressure Principle Assembly			RP <input checked="" type="checkbox"/> DCDA <input type="checkbox"/> DC <input type="checkbox"/> RPDA <input type="checkbox"/> PVB <input type="checkbox"/> Air Gap <input type="checkbox"/> SVB <input type="checkbox"/> AVB <input type="checkbox"/>
	Double Check Valve Assembly			
	Check Valve #1	Check Valve #2	Relief Valve	PVB/SVB
Initial Test	Leaked <input checked="" type="checkbox"/> Closed Tight <input type="checkbox"/> Held at 3.2 PSID	Leaked <input checked="" type="checkbox"/> Closed Tight <input type="checkbox"/> Held at _____ PSID	Did not Open <input checked="" type="checkbox"/> Opened at _____ PSID Buffer 3.2 PSID	AIR INLET Did not Open <input type="checkbox"/> Opened at _____ PSID
				CHECK VALVE Leaked <input type="checkbox"/> Held at _____ PSID
Repairs	Repaired <input type="checkbox"/>			Repaired <input type="checkbox"/>
Final Test	Closed Tight <input type="checkbox"/> Held at _____ PSID	Closed Tight <input type="checkbox"/> Held at _____ PSID	Opened at _____ PSID Buffer _____ PSID	AIR INLET Opened at _____ PSID CHECK VALVE Held at _____ PSID

Comments

The above report is certified to be true.	Line Pressure _____
	Held Backpressure <input type="checkbox"/>
	#2 Shutoff <input type="checkbox"/>
	Relief Valve Exercised <input type="checkbox"/>

	Date/Time	Tester	Signature	Tester #	Test Kit	Passed	Failed
Initial Test	01/04/23	Jason Nyberg		XC5236	01180720	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Repairs							
Final Test						<input type="checkbox"/>	<input type="checkbox"/>

Lupe Salinas <lupe@nibackflow.com>

[External] Invoice: #32563 VARIOUS College of DuPage Satellite Campus Reports

Lupe Salinas <lupe@nibackflow.com>

Wed, Jan 18, 2023 at 04:29 PM UTC

CC: Marina Mendez <marina@spielmanplumbing.com>, Ditchfield, David <ditchf@cod.edu>

BCC:

CAUTION: This email originated from outside of COD's system. Do not click links, open attachments, or respond with sensitive information unless you recognize the sender and know the content is safe.

Hello,

Attached to each invoice you can find the backflow reports for:

650 Pasquinelli Dr- Westmont

1223 Rickert Dr- Naperville

500 N. Kuhn Rd- Carol Stream

Kind regards,

Lupe Salinas

Northern Illinois Backflow, Inc.

(T) 630-231-1595 (24 hr)

(F) 630-231-0550

lupe@nibackflow.com

www.nibackflow.com

Gary Spielman Plumbing, Inc.

(T) 630-231-2725 (24 hr)

(F) 630-231-0550

www.spielmanplumbing.com

3 attachments

doc19492920230118102228.pdf

doc19493020230118102240.pdf

doc19493120230118102254.pdf